



COMPLETE RADIOLOGICAL SERVICES

Pictured below are two radioactive devices detected prior to being melted at steel mills



In May 2010, these two radioactive gauges were discovered entering steel mills in two separate loads of scrap metal - one in Alabama and the other in Pennsylvania.

- 1) It is a well-known fact that hundreds of radioactive sources are missing today. They are made of metal and often end up discarded as scrap.
- 2) Although we monitor inbound shipments, in many cases it is not enough.
- 3) Clean up efforts and facility down time can cost millions

Scrap monitoring programs must be routinely reviewed and improved to minimize the risk of contaminating the facility.

Applied Health Physics, Inc. offers a review of your current monitoring program, with recommendations to improve the ability to minimize the risk of contamination. Contact our office for details.

2986 Industrial Blvd., Bethel Park, PA 15102

Phone: (800) 332-6648 (412) 835-9555

Fax: (412) 835-9559

E-Mail address: ahp.inc@comcast.net

Web Page address: www.appliedhealthphysics.com